THE HONG KONG POLYTECHNIC UNIVERSITY

INDUSTRIAL CENTRE **Issue: 1**

NON BLOCK RELEASE TRAINING PROGRAM 2008/2009 (Sem 2) **Date: 8-Jan-09**

Progamme-Year: **43078-2** **Programme:** **ME DG 2**

Day of Week: **Wednesday** **Time:** **8:30-17:00**

Subject Code: IC348 **Subject Group:** 211

Subject Title: Appreciation of Manufacturing Processes

No. of Student: 76 **No. of Groups:** 8 (A-H)

Module / Room		**Week**	**23**	**24**	**25**	**26**	**27**	**28**
		Date	4-Feb-09	11-Feb-09	18-Feb-09	25-Feb-09	4-Mar-09	11-Mar-09
Integrated Training :	**Room**	**Day**	**12**	**13**	**14**	**15**	**16**	**17**
1. Induction, IC tour & mentors session	U202	0.5						
2. Design Review	U204a & U204b	0.5						
3. Hot Metal	W001/W002	1						
4. Plastics	W501g	1		EF	CD			
5. Sheet Metal/Welding	W001b	1	CD					
6. Surface Finish /PCM	W401	1	AB	JK		EF	CD	
7. Machining	U401	3	JK	AB	EF	CD	GH	
8. CNC	W501	2			GH	AB		
9. NCM	W503	1	EF	CD	AB			
10. Rapid Prototyping	W501	1.5	GH (am)		JK	JK (am)		
11. Rapid Tooling	W501	1.5	GH (pm)	GH		JK (pm)	JK	
12. QC & Measurement	W503	1						
13. Assembly / Presentation	U401	1						All

Important Notes to Trainee:

1. Total Training Period 16 days (120 Hrs)
2. Training Time: from 8:30 to 17:00 daily
3. Mentors are required to arrange a half hour meeting with his groups of students on the days highlighted
4. Long trousers, safety shoes with non-slip soles and PPE are required to be worn starting from day 2 onwards.

Subect Code: IC349 **Subject Group:** 211

Subject Title: Integrated Manufacturing Project **No. of Student:** 79

Module / Workshop	**Date**	11-Mar-09	18-Mar-09	25-Mar-09	1-Apr-09	8-Apr-09	15-Apr-09	22-Apr-09
	Week	**28**	**29**	**30**	**31**	**32**	**33**	**34**
IC1401 Integrated Engineering Projects (MU)		**All Students at Room U202 (8:30 - 12:15)**	All	All	All	All	All	All

IC349 manufacturing stage to be held in June 2009

Important Notes to Trainee:

Safety Shoes: Safety Shoes with non-slip soles and steel toe caps are required to be worn during workshop training. Students should bring their own safety shoes. Trainees are not required to wear safety shoes when taking lecture in Engineering Drawing, Safety and Computer Training.

Name Tag: For ease of identification, trainees are required to wear a name tag while under training at the IC.

For other information on IC training, please refer to IC Trainee Handbook. Electronic copy can be downloaded at http://www.ic.polyu.edu.hk/student_net/downloadform.htm