

## NON BLOCK RELEASE TRAINING PROGRAM 2009/2010 (Sem 1)

**Programme-Year:** 45087 **Department:** ISE Top-up DG 1  
**Subject Code:** IC235  
**Subject Title:** INTEGRATED PRACTICAL TRAINING  
**No. of Student:** 27, Gp A (7) Gp B (7) Gp C (7) Gp D(6) **No. of Groups:** 4  
**Day of Week:** Tuesday **Time:** 8:30-17:00

Task	Workshop	Room No.	Date Week Duration	8-Sep-09	15-Sep-09	22-Sep-09	29-Sep-09	6-Oct-09	13-Oct-09	20-Oct-09	27-Oct-09	3-Nov-09	10-Nov-09	17-Nov-09	24-Nov-09	1-Dec-09
				Wk 2	Wk 3	Wk 4	Wk 5	Wk 6	Wk 7	Wk 8	Wk 9	Wk 10	Wk 11	Wk 12	Wk 13	Wk 14
Introduction, IC Tour & Mentor session		U401a	8:30-9:30	ABCD												
Industrial Safety	Safety	U401a	9:30-12:30	ABCD												
Engineering Drawing Appreciation	PDU	U204b	13:30-17:00	ABCD												
Hot Metal	Foundry	W002	1 day		AB	CD										
Sheetmetal	Fabrication / Welding/PCM	W001	1 day								CD	AB				
Machining	Machining	U401	2.5 days		CD	AB	CD	AB					ABCD (am)			
CAM	CAM	W501	2 days				AB	CD	AB	CD						
NCM	NCM	W503	1.5 day						CD	AB			ABCD (pm)			
Plastics	Plastics	W501	1 day								A,B	CD				
Surface Finish	Plating	W401	1 day											AB	CD	
Assembly & Consolidation	Fitting/ presentation	U401	1 day													ABCD

**Important Notes to Trainee:**

**Safety Gears:** Long trousers and safety shoes with non-slip soles and steel toe caps are required to be worn during workshop training.

Students should bring their own safety shoes or long trousers. Trainees are not required to wear safety shoes or long trousers when taking lecture in Engineering Drawing, Safety and Computer Training.

**Mentors:** Mentors should arrange to meet students on the days highlighted with blue

**Project Title:** Mechanical Toy